

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

【書類番号】



Terufumi HARA et al. Q80576


CONNECTOR

Filing Date: March 19, 2004

Darryl Mexic 202-663-7909

1 of 12

Fig. 1




4 接続端子
10 コネクタ
11 ハウジング
11a 端子収容室
11b 外周壁
11c 隔壁(外壁)
14d 溝部

12: 係止部身
12a: 開口部
12e: 側壁(外壁)
12g: 一端面
12h: 第1係止突起
12j: 他端面
12n: 第2係止突起
13: 空洞部

【図2】

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
2 of 12


Fig.2



【図3】


Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
3 of 12

Fig.3



【图4】

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
4 of 12



【図6】




Fig. 6

【図 7】






Fig. 7



6. 19. 1941



整理番号 P 0 4 4 1 2 3

【図10】





Fig. 11



【図12】

Fig. 12

